




Chongqing BLSH Trading Co.,Ltd.

+86 18302333106 :Phone

Manager@blshdiesel.com :Email

www.blshdiesel.com :Website

No. 8, Xiyuan North Street, Shapingba District, Chongqing



B

S





Professional
service




Global
Network



Quality
Assurance

IDTECH ACTUATOR LIST									
IDTECH Part NO.	Actuator Kit or Actuator Part NO.	Interchange Part NO.(Other OEM Part Numbers That Will Work)	Turbo Model	Application-vechile model or engine mode	Picture	Wire &Connector	Collant port	Voltage	Note
ID001	4034315	4032772HX, 2836004, 2837675, 4032772 4034315RX, 4034315HX, 5452693	VGT Turbo HE300VG, HE351VE 3787604, 3787605, 5326057, 3798538, 3794757, 5501329, 3770973, 3775439	2013-2018 ISB6.7L Diesel, Dodge Ram Cummins				12V	OK completed verification
ID002	3777426	3777426(kit), 3785180	HE300VG, 3787604, 3787605, 5326057, 3798538, 3794757, 5501329, 3770973, 3775439	Doge Ram ISB6.7L				12V	OK completed verification
ID003	3788936	3788936, 3778619, 3778623, 3784299, 3784386, 3785180, 3788932, 4032067, 4032659, 4034090, 4034168, 4034193, 4034309, 4034315, 4034395, 5452689, 5454057, 5456327, 5459882, 5494878,5555542, 5579127, 5601240, 6374774, 6382096, 6447832, 68232771, 68244609AA, 68307025AA, 68445522AA, 68481772AA	HE300VG, HE351VE 3787604, 3787605, 5326057, 3798538, 3794757, 5501329, 3770973, 3775439, 3798378, 3789476, 3796038, 3796039, 3796040, 3798326, 3798327, 3798328, 3775413, 3775415, 3775417, 3781731, 3781732, 3781733, 3789474, 3789475, 5328155, 4309305, 4309307, 4309309, 4352193, 4352194, 4352195, 4352470, 4352471, 4352472, 4632166, 5328153, 5328154	2013+ Dodge Ram 2500 3500 4500 5500, Freightliner M2, medium-duty trucks, Cummins B6.7, ISB6.7				12V	OK completed verification
ID004	5325957	3788941,5325957(kit)	HE351VE, HE300VG, 2834603, 3770973, 3770974, 3799840, 3790483, 4046837, 4046836, 5608776, 6512310, 5325950, 5325947, 5322324	2007.5-2012 Dodge ISB 6.7L Dodge RAM 2500 3500		Wire PN:28091298		12V	OK completed verification
ID005	4032772	4046535, 4046534, 4032773RX, 4043827, 4045123, 4032773, 4032773NX, 4032772NX, 2837675, 4032772, 4032771, 4032659, 2836004, 4032163	HE300VG, HE351VE 2834603, 2834228, 2837665, 2881755, 2881847, 2882013, 2882075, 3770973, 3770974, 3799840, 3790481, 3790483, 4046837, 4046836, 5608776, 6512310, 5325950, 5325947, 5322324, 5322344, 5325957, 4955876	2003-2012 ISB 6.7L Diesel Dodge Ram Cummins		Wire PN:28091298		12V	OK completed verification
ID006	6382093	5459710, 5459710RX, 5358001RX, 5358454, 5358001, 5458936, 5458936H, 5458936HX, 5358452, 5351486, 5454978, 5454976, 5454977, 6382093, 6382093H, 6382093HX, 6382093RX, 6318455	Cummins X15 Holset HE400VG Turbo Cummins2020-2023 5327132, 5350586, 5351565, 5358003, 5358483, 5358484, 5358485, 5454983, 5454984, 5458937, 5459710, 5550895, 5550896, 6503103, 6395630, 5550894, 5550896, 5609888, 5457911	EPA17 Automotive 15 liter ISX/QSX engines, ISX15 - X15 Engine Turbocharger KENWORTH				12V	OK completed verification
ID007	5452695	4034188, 4034429, 4034429RX, 5355124, 5355724, 5356525, 5501185, 550118500, 550118500H, 550118500HX, 5501185H, 5501185HX, 5501185NX, 5501185RX	Cummins X15 Holset HE400VG Turbo Cummins2017-2019 5327132, 5350586, 5351565, 5358003, 5358483, 5358484, 5358485, 5454983, 5454984, 5458937, 5459710, 5550895, 5550896, 6503103, 6395630, 5550894, 5550896, 5609888, 5457911	for Newer ISX15 - X15 Engine Turbocharger KENWORTH				12V	OK completed verification
ID008	6382091(kit)	5452687, 5452690, 5550398, 5496045, 4034136, 4034397, 4034176, 4034091, 6382091, 6374773, 3778620, 3788938, 3784301,4034310	HE300VG, HE351VE 5351000, 5353210, 5640481, 5350999, 5501327	Cummins ISC, ISL, L9				12V	OK completed verification
ID009	5452692	5452692, 2192476PEX, 2296205PEX, 2348174PEX, 5324750, 5355872, 5455047, 5501183, 5699757	HE400VG, 5459128, 5548352, 2128151, 5642879, 5459132, 5459133, 2128150, 2308628, 5642882, 2348177, 5356656, 2121351, 701612AT	PACCAR MX11 MX13				12V	OK completed verification
ID010	4034287	3777282, 3777279, 3773519, 3773512, 3795555, 3795537, 3795557, 3793520, 3781421, 3781417, 3787563, 3790310, 3790308,4034287, 4034118, 4032765, 4032765	HE400VG, HE431VE 3777282, 3777279, 3773519, 3773512, 3795555	1. 2010- Cummins Industrial, Various QSL 8.9L engine. 2. Various 8.3L ISC engine		Wire PN:28390548	3&4&7	12V	OK completed verification
ID011	4034289	3776172, 2835940, 2837201, 3791991, 4032066, 4032673, 4032760, 4032760RX, 4032760NX, 4304208, 4034210, 4034289RX, 4042307, 4045108, 3789677, 4034289, 4034208, 4034116, 3789676, 6378270, 5638668	HE451VE, HE551VE, HE561VE, HE500VG 5457298, 5456024, 5354714, 5350499, 2882111, 2882112, 2843821, 4309077, 4309078	for Cummins ISX15 , ISM15, QSX15 KENWORTH Trucks		Wire PN:28390548	2&7	12V	OK completed verification
ID012	4034114	4032170, 4032798, 4034114, 403411400, 2837207, 3789659	HE400VG, HE431VE 3773442, 3780910, 3789659, 3789662, 4031000H, 4031238, 5451878	For Volvo 13.0L MD13, MD13 US07,D13B, MP7 EPA07, MP7 EPA10, MP8 EPA07 Diesel Engine for MACK Truck(2008-2015)		Wire PN:28390547	1&5	12V	OK completed verification
ID013	4034120	3787579, 4034120H, 23536422, R23536422, R23539062, R23536427, E23536427, 4032021, 2835948, 3787581, 4046366	HE531VE, HE500VG HE531VE, 23539570, 23536422, 23536802, 3792071, 3798597, 5329513, 5352845, 6437887, 23539062, 6347918	for 2004-2014 DaimlerFire Truck, Kenworth, Peterbilt, Freightliner, Various Trucks with 14.0L Detroit Diesel Series 60		线束PN: 28390549	1&5	12V	OK completed verification
ID014	5322882	2840930, 3787570, 3787571, 3789647, 5322874, 5322882, 1856274, 1975830, 4034284, 3787575, 4032845	HE400, HE400VG, HE431VE, HE451VE, HE531VE, HE531V, HE551VG 1944763, 2049933, 2052194, 2117933, 1831156, 2842125, 3791937, 5355091, 5355096, 2052194, 2117933, 1831156, 5351864, 5355112, 5322072, 6500123, 701169AT	PACCAR MX13, EPA10 engines			2 & 8	12V	OK completed verification

ID015	5355671	5355671, 5355673, 2140164	HE500VG, 5356675, 702192	PACCAR MX13			2 & 8	12V	OK completed verification
ID016	59001107417	59001107417, 12723306, 12708802, 12665348, 12683983		Duramax L5P 6.6L				12V	OK completed verification
ID017	59001107388	59001107388, 59001107387, 184300C92, 184300C93, 184300C94, 184300C95, 184300C96, 184300C97, 184300C98, 176013, 479514, 184303C1, 184303C2, 184303C3, 4307200R1, 4307201R1, 8C3Z-6K682-XXX	BV70, V2S	Pickup: F250/F350/F450/F550, Ford 6.4L				12V	OK completed verification



Big actuator collant port



BLSH

Chongqing BLSH Trading Co.,Ltd.

+86 18302333106 :Phone

Manager@blshdiesel.com :Email

www.blshdiesel.com :Website

No. 8, Xiyuan North Street, Shapingba District, Chongqing